

JDA A18-B17 Pipeline Project Progress

(February – March 2008)

- Milestone achievements (February – March 2008);
 - Flooding, cleaning, gauging and caliper survey started and completed.
 - Completed collecting the water sample for cleanliness analysis of pipeline.
 - ESDV actuator installation completed on CKR platform

- Current activity
 - Preparation for the pipeline hydrostatic test.

Photographs



Insert caliper pig for pipeline survey
ติดตั้งกระสวยเพื่อสำรวจภายในระบบท่อส่งก๊าซฯ



Insert caliper pig for pipeline survey
ติดตั้งกระสวยเพื่อสำรวจภายในระบบท่อส่งก๊าซฯ

Photographs



Flooding pump

ปั้มน้ำสำหรับทำความสะอาดท่อส่งก๊าซฯ และขับเคลื่อนกระสวย



Filter

กรองน้ำ

Photographs



ESDV actuator installation

ติดตั้งอุปกรณ์ปิด เปิดวาล์วฉุกเฉินบนแท่น



ESDV actuator installation

ติดตั้งอุปกรณ์ปิด เปิดวาล์วฉุกเฉินบนแท่น

Photographs



ESDV actuator installation


ติดตั้งอุปกรณ์เปิด ปิดวาล์วฉุกเฉินบนแท่น



ESDV actuator installation

ติดตั้งอุปกรณ์เปิด ปิดวาล์วฉุกเฉินบนแท่น

Diagram



Equipment diagram of flooding, cleaning, gauging and caliper survey of pipeline

แผนภาพอุปกรณ์สำหรับการทำความสะอาดและสำรวจระบบท่อส่งก๊าซ